

Liebherr Original Drive Shaft ID-No.944301703. FAT400 – FAT400P073. ER934, ER944, LOS934, LOS944, R906, R, R932, R942, R934, R942, R944. #OC2 2053#



Price: 320 (€)

Specifications

Spare Part Number: ID-No.944301703.

Suitable Machines: ER934, ER944, LOS934, LOS944, R906, R, R932, R942, R934, R942, R944.

Suitable Spare Parts: Traction Drive Type:FAT400 - FAT400P073.

Condition: Like New

Operating Hours: 1

Year of Construction: 2021

Serial Number: #OC2 2053#

Weight: 3

Dimensions: 23x12x12 cm

Additional Information

I am selling a Like New Liebherr Original Drive Shaft for Traction Drive Type:FAT400 - FAT400P073.

Original Liebherr Drive Shaft Spare Parts Number:ID-No.944301703.

Suitable for Liebherr Crawler Excavators Traction Drive with item code:

* 9443050 * 968744301 *

Suitable for Liebherr Crawler Excavators:

ER934 C-LC-1382, ER934C-LC-1382.

ER944 C-EW-1408, ER944 C-EW-1635.

LOS934 C-LC-1382, LOS934 CHDSL-918, LOS934 VH-033.

LOS944 HDSL-651, LOS944B HDSL-1075.

R906 WLC-1449.

R916 LC-1301.

R932 T-605, R932 TU-605, R932 TUN-605, R932 TUN.-605, R932-605.

R934 B-SHD-926, R934 BVHHD-975, R934 C-1439, R934 C-HDS-016, R934 C-LC-1337, R934 C-LC-1375, R934 C-NLC-1335, R934 C-SHD-023, R934 CSHD-023, R934 CVHHD-033, R934 HDS-647, R934 HDS-731, R934 HDSL-648, R934 HDSL-731, R934 T-974, R934B HDS-923, R934B S-HD-926, R934B SHD-926, R934B VH-HD-975, R934C LC-1439.

R942 BRA-531, R942 EW-574, R942 EW-616, R942 HD-S-573, R942 HD-SL-574, R942 HDS-573, R942 HDSL574, R942 SL-574, R942-365, R942-573, R942-574, R942-616.

R944 B HDS-650, R944 B HDSL-651, R944 B-EW-653, R944 B-HDS-650, R944 BHDS-650, R944 BHDSL-1075, R944 BHDSL-651, R944 C T-169, R944 C TUN-169, R944 C-169, R944 C-791, R944 C-EW-793, R944 C-HDS-786, R944 C-LC-1339, R944 C-LC-1446, R944 C-NLC-1338, R944 CHDS-786, R944 CHDSL-1164, R944 CHDSL-791, R944 CT-169, R944 EW-653, R944 HDS-650, R944 HDS-651, R944 HDS-654, R944 HDSL-651, R944 LBR-651, R944 T-169, R944-1441, R944B BHDS-650, R944B EW-653, R944B HDS-651, R944B HDSL-1075, R944B HDSL-650, R944B HDSL-651, R954C HDSL-1164, R944C HDL-791, R944C LC-1441.

The Original Liebherr Drive Shaft is in Like New Condition.

!! Original Liebherr Drive Shaft in excellent Like New Condition !!

For inquiries or to arrange a viewing, please do not hesitate to contact me.