Karantzounis Construction Machinery & Spare Parts

Virchowstrasse 25/6, 89075 Ulm, Deutschland | 00497313799306, 00491608231509 | info@karantzounis.de

Liebherr Drive Shaft ID-No.969527001. FAT355P077. LH26, LH30, R906, R916, R920, R922, R924, R926 COMP, R926. #ANT2804#



Price: Ask For Price (€)

Specifications

Spare Part Number: ID-No.969527001

Suitable Machines: LH26, LH30, LOS1926, LOS926, R906, R916, R920, R922, R924, R926.

Suitable Spare Parts: Traction Drive Type:FAT355P077.

Condition: Like New

Operating Hours: 1

Year of Construction: 2022

Serial Number: #ANT2804#

Weight: 3

Dimensions: 20x10x10 cm

Additional Information

I am selling a new Liebherr Drive Shaft for Traction Drive Type:FAT355P077

Liebherr Drive Shaft Space Parts Number:ID-No.969527001.

Suitable for Liebherr Crawler Excavators Traction Drive with item code:

* 969526501 *

Suitable for Liebherr Wheeled Excavators:

LH26 EC-1704.

LH30 C-1210, LH30 C-1526.

Suitable for Liebherr Crawler Excavators Traction Drive with item code:

* 969526501 *

Suitable for Liebherr Crawler Excavators:

LOS1926 LC-1488.

LOS926K-LC-1565, LOS926 LC-1488.

R906 LC-1283, R906 LC-1285, R906 NLC-1141, R906 NLC-1144, R906 NLC-1283,
R906 S-1139, R906 S-1142, R906 WLC-1140, R906 WLC-1143.

R916 LC-1021, R916 LC-423, R916 NLC-1025, R916 NLC-1086, R916 SLC-1306,
R916 SLC-1307, R916 SLC-1462, R916 SLC-1501, R916 WLC-1274, R916 WLC-1344,
R916 XLC-1721.

R920 S-1545.

R922 LC-1379, R922 LC-1442, R922 LC-1443, R922 NLC-1314, R922 SLC-1315,
R922 XLC-1677.

R924LC-1318, R924 LC-1444, R924 LC-1445, R924 NLC-1316, R924 SLC-1317,
R924 WLC-1347.

R926 CL-1022, R926 COMP-1298, R926 COMP-1299, R926 K LC-1298, R926 K-LC-1565,
R926 K-LC-1827, R926 LC-1022, R926 LC-1026, R926 LC-1235, R926 LC-1302,
R926 LC-1320, R926 LC-1471, R926 LC-1488, R926 NLC-1027, R926 NLC-1087,
R926 NLC-1319, R926 NLC-1488, R926 PROTO-1026, R926 SLC-1345, R926 SLC-1346,
R926 SLC-1348, R926 SLC-1488, R926 SLC-1502, R926 WLC-1023, R926 WLC-1321,
R926 WLC-1488, R926 WLC-692.

The Drive Shaft is in New Condition.

!! It is a new Drive Shaft !!

If you have any questions or visits, please feel free to contact me.