


Liebherr Original Pipe Fraction Safety Valve with ID-No.5009808- ID-No.5009494-ID-No.5009624.

A308,A309,A310,A311,A312,A314,A316,A900,A904,A910,A912,A914,A916,A918COMP.



Price: 900 (€)

Specifications

Spare Part Number: ID-No.5009808 - ID-No.5009494 - ID-No.5009624.

Suitable Machines:

Type:A308,A309,A310,A311,A312,A314,A316,A900,A904,A914,A916,A918COMP,A920,A922RAIL,A924,A944,LH22,LH30,R308,R310,R312,R313,R317,R900,R904,R906,R914,COMP.

Suitable Spare Parts: Pipe Fraction Safety Valve

Condition: Like New

Operating Hours: 1

Year of Construction: 2008

Serial Number: #5009808.31.03#

Weight: 8

Dimensions: 20x15x15 cm

Additional Information

I am selling a New Original Liebherr Pipe Fraction Safety Valve.

Original Liebherr Pipe Fraction Safety Valve Spare Parts Number:ID-No.5009494
ID-No.5009624 - ID-No.5009808.

Suitable for Liebherr Wheeled Excavators Slewing Drive with item code:

* 9280820 * 9282184 * 9282509 * 9282943 * 9283067 * 9284993 * 9286166 * 9287656 *
* 9288663 * 94003911 * 94013483 * 94013503 * 94015836 * 94015844 * 94016537 *
* 94020239 * 94020403 * 94020304 * 94020967 * 94020984 * 94024735 * 94024736 *
* 94025178 * 94031886 * 94031887 * 94038800 * 94053496 * 94053497 * 94053548 *

* 94053549 * 94053554 * 94053555 * 94078983 * 9580966 * 9585639 * 9586584 *
* 9587474 * 9588546 * 9589042 * 9589481 * 9596958 * 9598787 * 9600144 * 9614648 *
* 9626607 * 9627715 * 9642621 * 9642632 * 9642663 * 9806871 * 9824036 * 9828095 *
* 9828096 * 9917034 * 9917246 * 9919380 * 9919797 * 9919800 * 9919803 * 9919805 *
* 9919811 * 9919813 * 9919815 * 9919817 * 9920190 * 9920219 * 9920223 * 9920253 *
* 9920254 * 9920256 * 9920259 * 9920262 * 9920272 * 9920274 * 9920276 * 9920280 *
* 9920282 * 9920286 * 9921467 * 9923195 * 9925109 * 9925390 * 9925606 * 9925738 *
* 9950111 * 9950114 * 9950140 * 9955243 * 9955245 * 9955281 * 9955298 * 9955318 *
* 9955336 * 9955470 * 9955470 * 9955702 * 9955726 * 9955762 * 9955797 * 9955797 *
* 9955805 * 9955985 * 9956022 * 9956053 * 9956074 * 9956092 * 9956130 * 9956443 *
* 9957235 * 9957237 * 9957241 * 9957243 * 9958186 * 9958367 * 9958378 * 9958386 *
* 9958390 * 9958395 * 9958398 * 9958856 * 9958858 * 9959072 * 9959930 * 9959932 *
* 9961251 * 9961286 * 9961290 * 9962716 * 9963384 * 9963386 * 9963388 * 9964204 *
* 9964221 * 9964223 * 9964243 * 9964245 * 9964258 * 9964260 * 9965350 * 9965904 *
* 9966536 * 9967209 * 9967480 * 9967485 * 9967489 * 9967571 *

Suitable for Liebherr Wheeled Excavators:

A308-374.

A309 LI-1035, A309 LI-717, A309 LI717-717.

A310-567.

A311 LI-1037, A311 LI-718, A311 LI718-718.

A312 LI-1037, A312 LI-719, A312-551.

A314 LI-1039, A314 LI-635.

A316 LI-1040, A316 LI-1041, A316 LI-7106, A316 LI-716,
A316 LI717-715, A316 LI716-716, A316-617, A316-691.

A900 B-LI-662.

A900 C-LI-1002, A900 C-LI-917, A900 C-LI-98.
A900 C-ZW-1030, A900 C-ZW-1031, A900 C-ZW-1032, A900 C-ZW-1033,
A900 C-ZW-1384, A900 C-ZW-1385, A900 C-ZW-729, A900 C-ZW-730,
A900 C-ZW-931.

A900 ZW-612, A900 ZW-613, A900 ZW-928, A900 ZW-972.
A900-308.

A904 C-LI-1003, A904 C-LI-1004, A904 C-LI-1005, A904 C-LI-1071,
A904 C-LI-439, A904 C-LI-440, A904 C-LI-441.

A904 IND-710, A904 IND-711.

A904 LI-665, A904 LI-666, A904 LI-667, A904 LI-720.

A910 COMP-1186.

A912 COMP-1187.

A914 COMP-1188, A914-1176.

A916-1177.

A918 COMP-1189, A918 COMP-1192, A918-1178.

A920-1179.

A922 RAIL-1190.

A924 RAIL-1191.

A944 C-LI-196.

LH22 C-1209, LH22 M-1197.

LH24 M-1198.

LH26 EC-1704, LH26 M-1199.

LH30 C-1526, LH30 M-1200.

LOS103.

R308-375.

R310-568.

R312-552.

R313 LI-1038, R313 LI-636.

R317 LI-1042, R317 LI-1043, R317 LI-362, R317 LI-970.

R900 B-LI-664, R900 B-LI-762, R900 B-LI-970.

R900 C-LI-1076, R900 C-LI-971, R900 C-LI-981, R900 C-LI-982.

R914 COMP-1194.

Suitable for Liebherr Crawler Excavators Traction Drive with Item.Code:

* 10049816 * 10054163 * 10054270 * 10060749 * 10075301 * 10082896 * 10086442 *
* 10371254 * 10391069 * 10393608 * 10406211 * 10843651 * 10860455 * 98006871 *
* 9808930 * 9824036 * 9827326 * 9828095 * 9828096 * 9896226 * 9920253 *
* 9920254 * 9920256 * 9920259 * 9920262 * 9927229 * 9942079 * 9946705 *
* 9948435 * 9959932 * 9967209 *

Suitable for Liebherr Crawler Excavators:

LO1904 CHDSL-983.

LO1924 COMP-1056.

LOS904 C-412, LOS904CHDSL-983, LOS904 CHDSL-985, LOS904 HDSL-668, LOS904 STD-669,

LOS904-668, LOS904-669, LOS904-679, LOS904-694, LOS904C HDSL-983, LOS904C STD-984.

LOS924 COMP-1055, LOS904 COMP-1056, LOS924 COMP-196, LOS924 COMPT-1083, LOS924 CT-1083.

LOSR904 HDSL-668, LOSR904-669.

P904 HDSL-668, P904 OBW-983.

R904 C STD-984, R904 C-1017, R904 C-984, R904 C-EW-993, R904 C-STD-984, R904 CHDSL-983, R904 CHDSL-985, R904 EW-670, R904 HDSL-668, R904 HDSL-669, R904 HDSL-694, R904 S-LC-733, R904 SLC-733, R904 STD, R904C HDSL, R904C STD-669, R904C HDSL-983, R904C HDSL-985, R904C STD-984.

R906 LC-1285.

R914 BHDSL-1061, R914 STAM-640, R914B STAM-960.

R924 COMP-1055, R904 COMP-1056, R924 COMP-1083, R924 COMP-911, R924 COMPT-1083, R924 CT-1083.

R930 T-1980.

!! This is a New Original Liebherr Pipe Fraction Safety Valve !!

The Original Liebherr Pipe Fraction Safety Valve are in New Condition.

For inquiries or to arrange a viewing, please do not hesitate to contact me.