

Liebherr Output Shaft ID-No.932919701. SAT350/208 – SAT350/252. A954B, A954C, LH80 C, LH80 M, R954CG, E954, EP954, ER954, P954C, P954E, R954B, R954C. #932919701.27.12#



Price: Ask For Price (€)

Specifications

Spare Part Number: ID-No.932919701.

Suitable Machines: Type:A954B, A954C, LH80 C, LH80 M, R954CG, E954, EP954, ER954, P954C, P954E, R954B, R954C.

Suitable Spare Parts: Slewing Drive
Type:SAT350/208 - SAT350/252.

Condition: Like New

Operating Hours: 5

Year of Construction: 2023

Serial Number: #932919701.27.12#

Weight: 53

Dimensions: 43x21x21 cm

Additional Information

I am selling a Like New Liebherr Output Shaft for Slewing Drive Type:SAT350/208 - SAT350/252.

Liebherr Output Shaft Spare Parts Number:ID-Nr.932919701.

Suitable for Liebherr Wheeled Excavators Slewing Drive with item code:

**** 932909501 * 933380101 ****

Suitable for Liebherr Wheeled Excavators:

A954 B-LI-714, A954 C-LI-450, A954 LI-614.

LH80 C-1213, LH80 C-1529, LH80 EC-1676, LH80 M-1205, LH80 M-1218,
LH80 MHR-1205, LH80 MHR-1218, LH80 MP-1218, LH80 MPHR-1218.

R954 CG-1255.

Suitable for Liebherr Crawler Excavators Slewing Drive with item code:

**** 932909501 * 933380101 ****

Suitable for Liebherr Crawler Excavators:

E954 C-HR-1380, E954-702.

EP954 C-1326, EP951 C-1431.

ER954 C-HR-1380, ER954 C-SEW-1425, ER954 SEW-1425.

P954 C-783, P954 E-702.

R954 B-EW-632, R954 B-HD-629, R954 B-HDS-633, R954 B-HDV-631, R954 B-HDW-631, R954 B-V-630, R954 BV-HD-708, R954 BVHDW-695, R954 BVHHD-736, R954 C HD-1661, R954 C HR-1016, R954 C LCV-1615, R954 C-EW-783, R954 C-HDV-781, R954 C-HDW-781, E954 C-SEW-1374, R954 CHDEW-1390, R954 CHDW-781, R954 CHR-1016, R954 CSEW-1341, R954 CSEWH-1374, R954 CVHHD-1175, R954 CVHHD-1276, R954 HD-494, R954 HD-EW-557, R954 HD-S-562, R954 HD-W-569, R954 HDS-633, R954 HDW-569, R954 HDW-631, R954 HDW-781, R954 LC-VW-1698, R954 V-406, R954 VH-HD-1175, R954-406, R954-569, R954-629, R954B BVHHD-736, R954B EW-632, R954B HD-629, R954 HDS-633, R954B HDSL-633, R954B HDW-631, R954B HDW-632, R954B V-630, R954 V-HD-708, R954B VHD-708, R954 VHHD-736, R954C LC-VW-1698.

The Output Shaft is in Like New Condition.

!! It is a Like New Output Shaft !!

If you have any questions or visits, please feel free to contact me.