


Liebherr Sun Wheel ID-No.9443047 – ID-No.944304703 – ID-No.90209442. A914 B,A914 C,A924,A932,A934,LH30,LH35,P924 C,E932,P914,P924 COMP,R906,R914,R916,R924,R926,R930 T,R932,R934,R944. #90209442.02.10#



Price: Ask For Price (€)

Specifications

Spare Part Number: ID-No.944304703 - ID-No.9443047 - ID-No.90209442.

Suitable Machines: A914 B, A914 C, A924, A932, A934, LH30, LH35, P924 C, E932, P914, P924 COMP, R906, R914, R916, R924, R926, R930 T, R932, R934, R944.

Suitable Spare Parts: Slewing Drive
Type:SAT275/222, SAT275/233, SAT275/235, SAT275/236, SAT275/237, SAT275/238, SAT275/261, SAT275/266, SAT275/289.

Condition: New

Operating Hours: 1

Year of Construction: 2025

Serial Number: #90209442.17.02#

Weight: 1

Dimensions: 7x6x6 cm

Additional Information

I am selling a New Genuine Liebherr Sun Wheel for Slewing Drive Type:SAT275/222, SAT275/233, SAT275/235, SAT275/236, SAT275/237, SAT275/238, SAT275/261, SAT275/266, SAT275/289.

Liebherr Sun Wheel Spare Parts Number:ID-No.944304703 - ID-No.9443047 - ID-No.90209442.

Suitable for Liebherr Wheeled Excavators Slewing Drive with item code:

* 90017908 * 932083301 * 932083401 * 9443065 * 9443880 * 9443950 * 9444350 *

* 9444360 * 968725701 * 968866301 * 968866401 * 969255701 * 90203091 * 13463365 *

Suitable for Liebherr Wheeled Excavators:

A914 B-LI-954, A914 B-LI-955, A914 C-LI-1044, A914 C-LI-1045, A914 LI-671,
A914 LI-672.

A924 HL-1206, A924-1206.

A924 B-LI-956, A924 B-LI-957, A924 B-LI-958, A924 B-LI-959, A924 C-LI-1047,
A924 C-LI-1048, A924 C-LI-1049, A924 C-LI-1050, A924 C-LI-1051, A924 C-LI-1305,
A924 C-LI-1313, A924 LI-674, A924 LI-675, A924 LI-687, A924 LI-709, A924 LI675-675,
A924 LI687-687, A924 LI709-709, A924-1180.

A928-1181.

A932 LI-360, A932 LI-361, A932 LI-685.

A934 B-LI-934, A934 B-LI-935, A934 C-LI-1006, A934 C-LI-1007, A934 C-LI-1053,
A934 LI-712, A934 LI-713.

LH30 C-1210, LH30 C-1526, LH30 M-1200, LH30 M-1253.
LH35 M-1201, LH35 M-1254, LH35 MT-1220, LH35 MT-1473.

P924 C-LI-1292.

Suitable for Liebherr Crawler Excavators Slewing Drive with item code:

* 932083301 * 932083401 * 9443065 * 9443880 * 9443990 * 9443950 * 9444350 *
* 9444360 * 968725701 * 968866101 * 968866201 * 968866301 * 968866401 *
* 969255701 * 969386801 * 970244401 * 90015894 * 90207735 * 90207740 *

Suitable for Liebherr Crawler Excavators:

E932 LI-488, E932 P-1070, E932 P-1089, E932 P-448, E932-1089, E932-488, E932-621.

LOS1906 NLC-1141, LOS 914 HDSL-947, LOS914-640, LOS934-648.

P914 CHDSL-1062, P914B-960, P924 COMP-1055, P924 OBW-1066, P924C HDSL-1066,
P932 E-488, P932-571, P934-648, P934 PONT-735, P934C OBW-027.

R906 C LC-1283, R906 C-1283, R906 C-LC-1283, R906 LC-1283, R906 LC-1285, R906 NLC-1141,
R906 NLC-1144, R906 NLC-1283, R906 S-1139, R906 S-1142, R906 WLC-1140, R906 WLC-1143,
R906 WLC-1449.

R914 B STD-964, R914 B-SLC-1019, R914 B-STD-964, R914 BEW-966, R914 BHDS-963,
R914 BHDSL-1061, R914 BHDSL-960, R914 BHDSL-961, R914 BHDSL-962, R914 C HDL-1063,
R914 C HDS-1065, R914 CHDSL-1062, R914 CHDSL-1063, R914 CHDSL-1064, R914 CHDSL-1065,
R914 EW-643, R914 HDS-642, R914 HDSL-1062, R914 HDSL-640, R914 HDSL-642, R914 HDSL-680,
R914 HDSL-681, R914 HDSL-727, R914 HDSL-947, R914 PROTO-640, R914 STAM-640, R917 STD-641,
R914 STD-658, R914 VH-756, R914B FOTON-1054, R914B HDS-963, R914B HDSL-1054, R914B HDSL-640,
R914B HDSL-960, R914B HDSL-961, R914B HDSL-962, R914B STAM-960, R914B STD-964.

R916 LC-1021, R916 LC-1301, R916 LC-423, R916 NLC-1025, R916 NLC-1086, R916 S-1020,

R916 SLC-1306, R916 SLC-1307, R916 WLC-1274, R916 WLC-1344.

R924 BEW-969, R924 BHDSL-761, R924 BHDSL-967, R924 BHDSL-968, R924 C EW-1069, R924 C-1066, R924 CEW-1069, R924 CHDSL-1066, R924 CHDSL-1067, R924 CHDSL-1068, R924 COMP-1055, R924 COMP-1056, R924 COMP-1083, R924 COMPT-1083, R924 CT-1083, R924 CVDHD-1136, R924 CVH-1174, R924 CVHHD-1136, R924 EW-646, R924 HDSL-645, R924 HDSL-676, R924 HDSL-677, R924 HDSL-761, R924 VH-734, R924 VH-740, R924B EW-969, R924B HDSL-1073, R924B HDSL-761, R924B HDSL-967, R924B HDSL-968, R924B VH-HD-794, R924B VHHD-794.

R926 CL-1022, R926 LC-1022, R926 LC-1026, R926 LC-1302, R926 NLC-1027, R926 NLC-1087, R926 PROTO-1026, R926 SLC-1345, R926 SLC-1346, R926 WLC-1023, R926 WLC-692.

R930 T-1980.

R932 EW-405, R932 EW-590, R932 HD-EW-590, R932 HD-S-381, R932 HD-S-571, R932 HD-SL-365, R932 HD-SL-572, R932 HDS-571, R932 HDSL-572, R932 LI-571, R932 OBW-571, R932 SL-572, R932 T-564, R932 T-605, R932 T-BG-564, R932 TU-605, R932 TUN-561, R932 TUN-605, R932 TUN -605, R932-365, R932-381, R932-405, R932-561, R932-564, R932-571, R932-572, R932-590, R932-605.

R934 B HDS-923, R934 B HDSL-924, R934 B-SHD-926, R934 BEW-925, R934 BHDS-923, R934 BHDSL-924, R934 BVHHD-975, R934 C EW-027, R934 C-EW-027, R934 C-HDS-016, R934 C-SHD-023, R934 CSHDS-016, R934 CHDSL-1088, R934 CHDSL-918, R934 CSHD-023, R934 EW-649, R934 HDS-647, R934 HDS-648, R934 HDS-731, R934 HDS-923, R934 HDSL-648, R934 HDSL-731, R934 HDSL-924, R934 T-974, R934 TR-682, R934 TR.-682, R934 V-700, R934B EW-925, R934B HDS-923, R934B HDS-924, R934 HDSL-107 R934 HDSL-923, R934 HDSL-924, R934B S-HD-926, R934B SHD-926, R934 VH-HD-975.

R944 C T-169, R944 C TUN-169.

The Sun Wheel is in New Condition

!! This is a New Genuine Liebherr Sun Wheel !!

If you have any questions or visits, please feel free to contact me.