Karantzounis Construction Machinery & Spare Parts

Virchowstrasse 25/6, 89075 Ulm, Deutschland | 00497313799306, 00491608231509 | info@karantzounis.de

Liebherr Tapered Roller Bearing ID-No.10168061. SAT275A1211, SAT275/255, SAT275/261, SAT275/266, SAT275/289, SAT300/262, SAT275/263. A924, A934, LH30, LH35, R934, R906, R916, R926, R934.



Price: Ask For Price (€)

Specifications

Spare Part Number: ID-No.10168061

Suitable Machines: Type:A924,A934,LH30,LH35,R906,R916,R922,R924COMP

Suitable Spare Parts: Slewing DriveType:SAT275A1211,SAT275/255,SAT275/261,SAT275

Condition: New

Year of Construction: 2021

Weight: 8

Additional Information

I am selling a New Liebherr Tapered Roller Bearing for Slewing Drive Type:SAT275A1211, SAT275/255, SAT275/261, SAT275/263, SAT275/266, SAT275/289, SAT300/262, SAT300/263.

Liebherr Tapered Roller Bearing Spare Parts Number:ID-No.10168061.

Suitable for Liebherr Wheeled Excavator Slewing Drive with item code:

** 13453156 ** 13463365 ** 90017908 ** 90021732 ** 90027837 **

** 90203091 ** 90208852 ** 968725701 ** 969257101 ** 969313301 **

Suitable for Liebherr Wheeled Excavators:

A924 HL-1206, A924-1180, A924-1206.
A928-1181.
A934 B-LI-934, A934 B-LI-935, A934 C-LI-1006, A934 C-LI-1007, A934 C-LI-1053, A934 C-LI-1418, A934 C-LI-1419, A934 C-LI-1498, A934 C-LI-1499.
LH30 C-1210, LH30 C-1526, LH30 M-1200, LH30 M-1253.
LH35 M-1201, LH35 M-1254, LH35 MT-1220, LH35 MT-1473.
LOS-103.

R934 IND-1440.

Suitable for Liebherr Crawler Excavators Slewing Drive with item code:

** 90015402 ** 90015894 ** 90018668 ** 90027836 ** 90202420 **
** 90205057 ** 90205080 ** 90207735 ** 90207740 ** 90214085 **
** 968725701 ** 969257101 ** 969313301 ** 969386801 ** 970244401 **

Suitable for Liebherr Crawler Excavators:

E934 P-1295.
EP934 C HP-1613, EP934 C LP-1610, EP934 C-1295, EP934 C-1429,
EP934 C-1684, EP934 HP-1613, EP934-1294.
ER934 C EW-1361, ER934 C HR-1504, ER934 C SEW-1239, ER934 C-EW-1361,
ER934 C-EW-1593, ER934 C-LC-1382, ER934 EW-1361, ER934 HR-1504,
ER934 SEW-1239, ER934-1361, ER934C LC-1382.
LOS1906 NLC-1141, LOS934 C-LC-1382.
P924 COMP-1055.
P926 LC-1320.
P934C OBW-027.
R906 C LC-1283, R906 C-1283, R906 C-LC-1283, R906 LC-1140, R906 LC-1140,
R906 LC-1283, R906 LC-1285, R906 NLC-1141, R906 NLC-1144, R906 NLC-1283,
R906 S-1139, R906 S-1142, R906 WLC-1140, R906 WLC-1143, R906 WLC-1449.
R916 LC-1021, R916 LC-1301, R916 LC-423, R916 NLC-1025, R916 NLC-1086,
R916 S-1020, R916 NLC-1025, R916 NLC-1086, R916 S-1020, R916 SLC-1306,
R916 SLC-1307, R916 SLC-1462, R916 SLC-1501, R916 WLC-1274, R916 WLC-1344,
R916-1301.
R922 LC-1315, R922 LC-1379, R922 NLC-1314, R922 SLC-1315, R922 XLC-1677,
R922-1486.
R924 COMP-1055, R924 COMP-1056, R924 COMP-1083, R924 COMPT-1083,
R924 CT-1083, R924 LC-1318, R924 NLC-1316, R924 SLC-1317, R924 WLC-1347,
R924-1487.
R926 CL-1022, R926 COMP-1298, R926 COMP-1299, R926 K LC-1298,
R926 K LC-1565, R926 K LC-1827, R926 LC-1022, R926 LC-1026, R926 LC-1235,
R926 LC-1302, R926 LC-1320, R926 LC-1471, R926 LC-1488, R926 PROTO-1026,
R926 SLC-1345, R926 SLC-1346, R926 SLC-1348, R926 SLC-1488, R926 SLC-1502,
R926 WLC-1023, R926 WLC-1321, R926 WLC-1488, R926 WLC-962.
R930 T-1980.
R934 BHDS-923, R934 BHDSL-1074, R934 BHDSL-924, R934 C EW-027,
R934 C-1439, R934 C-EW-027, R934 C-HDS-016, R934 C-LC-1337, R934 C-LC-1375,
R934 C-NLC-1335, R934 C-SHD-023, R934 CEW-027, R934 CHDS-016,
R934 CHDSL-1088, R934 CHDSL-918, R934 CSHD-023, R934 CVHHD-033, R934 EW-1424,
R934 EW-649, HDS-647, R934 HDSL-648, R934 T-974, R934B EW-1424, R934B EW-925,
R934B HDS-923, R934B HDSL-1074, R934B HDSL-924, R934B SHD-926, R934C LC-1439.
R944 C T-169, R944 C TUN-169, R944 C-169, R944 CT-169, R944 T-169.

!! It is a New Tapered Roller Bearing !!

If you have any questions or visits, please feel free to contact me.