

**Liebherr Drive Shaft ID-No.9443786 – ID-No.944378603. FAT550  
FAT550P046. A900, LH120, LH150, E974, ER974, LOS1976, LOS-  
413, R964, R966, R970, R974, R976, R980, R984.  
#944378603.2374#**



**Price:** Ask For Price (€)

**Specifications**

**Spare Part Number:** ID-No.9443786 - ID-No.944378603.

**Suitable Machines:** A900, LH120, LH150, E974, ER974, LOS1976, LOS-413, R964, R966, R970, R974, R976, R980, R984.

**Suitable Spare Parts:** Traction Drive Type:FAT550 - FAT550P046.

**Condition:** Like New

**Operating Hours:** 120

**Year of Construction:** 2022

**Serial Number:** #944378603.2374#

**Additional Information**

I am selling a Like New Liebherr Drive Shaft for Traction Drive  
Typ:FAT550 - FAT550P046.

Liebherr Drive Shaft Spare Parts Number:ID-No.9443786 - ID-No.944378603.

Suitable for Liebherr Wheeled Excavators Traction Drive with item code:

\* 9443780 \* 944378003 \*

Suitable for Liebherr Wheeled Excavators:

A900 B-LI-662.

LH120 C-1103, LH120 CG-1103.

LH150 CHR-1231, LH150 ECG-1229, LH150 ECHR-1229.

Suitable for Liebherr Crawler Excavators Traction Drive with item code:

\* 90008209 \* 9443780 \* 944378003 \* 90212010 \*

Suitable for Liebherr Crawler Excavators:

E974B R-980, E974B-980.

ER974 B HD-1688, ER974 B-1688, ER974-980, ER974B HD-980, ER974B-980.

LOS1976-1402.

LOS-412.

LOS974 B-HD-737.

R964 BHDSL-760, R964 BSHD-938, R964 C SHD-1009, R964 C SHD-1278,  
R964 C-SHD-1278, R964 CSHD-1009, R964 CSHD-1278, R964 CSHD-1447,  
R964 CSHD-1448, R964 HDS-752, R964 SHD-1009, R964 SHD-938,  
R964B HDSL-760, R964B SHD-938.

R966 S-HD-1535, R966 S-HD-1359.

R970 S-HD-1538, R970 S-HD-1571, R970 S-HD-1572, R970 S-HD-1772,  
R970 S-HD-1784, R970 SME-1400, R970 SME-1401.

R974 B HD-408, R974 B-408, R974 B-601, R974 B-EW-796, R974 B-HD-408,  
R974 B-HD-737, R974 B-HD-949, R974 B-LI-737, R974 BEW-608, R974 BEW-914,  
R974 BHD-949, R974 BHDSL-451, R974 BHDSL-601, R974 BHDSL-737,  
R974 BHDSL-742, R974 BHDSL-949, R974 BHDSL-988, R974 BHR-951,  
R974 C HD-1137, R974 C HD-449, R974 C-HD-1137, R974 C-HD-1365,  
R974 C-HD-1371, R974 C-HD-449, R974 C-HR-1059, R974 C-LCV-1417,  
R974 CHDSL-1124, R974 CHDSL-1010, R974 CHR-1059, R974 CLCV-1417,  
R974 HD-408, R974 HD-449, R974 HD-585, R974 HDSL-601, R974 HDSL-742,  
R974 -408, R974-601, R974B EW-914, R974B HD-408, R974B HD-737,  
R974B HD-949, R974B HDSL-451, R974B HDSL-585, R974B HDSL-601,  
R974B HDSL-742, R974B HDSL-913, R974B HDSL-988, R974B HR-951,  
R974B LIT-408.

R976 HD-1402, R976 HD-1428, R976 HD-1460, R976 HD-1540, R976 HD-1574,  
R976 HD-1773, R976 HD-1785, R976 HD-SL-1540, R976 HDSL-1645, R976 LC-V-1461,  
R976 LC-V-1540, R976 LC-V-1573, R976 LC-V-1773, R976 LC-V-1785.

R980 S-HD-1786.

Suitable for Liebherr Mining Excavator Traction Drive with item code:

\* 9443780 \*

Suitable for Liebherr Mining Excavators:

R984-409.

The Drive Shaft is in Like New Contition.

!! It is a Like New Drive Shaft !!

If you have any questions or visits, please feel free to contact me.