

**Liebherr Multi-Disc Carrier ID-No.9443788 – ID-No.944378803.
FAT550, FAT550P046, FAT550P050, FAT600P081, FAT1000/102.
#9443788.23.03#**



Price: Ask For Price (€)

Specifications

Spare Part Number: ID-No.9443788 - ID-No.944378803.

Suitable Machines: A900, LH120, LH150, E974, ER974, LOS1976, LOS-413, R964, R966, R970, R974, R976, R980, R984, R9100, R9250, R9350, R994.

Suitable Spare Parts: Traction Drive Type:FAT550, FAT550P046, FAT550P050, FAT600P081, FAT1000/102.

Condition: Like New

Operating Hours: 20

Year of Construction: 2022

Serial Number: #9443788.23.03#

Weight: 2

Dimensions: 11x9x9 cm

Additional Information

I am selling a Like New Liebherr Multi-Disc Carrier for Traction Drive Type:FAT550, FAT550P046, FAT550P050, FAT600P081, FAT1000/102.

Liebherr Multi-Disc Carrier Spare Parts Number:ID-No.9443788 - ID-No.944378803.

Suitable for Liebherr Wheeled Excavators Traction Drive with item code:

* 9443780 * 944378003 * 932200801 *

Suitable for Liebherr Wheeled Excavators:

A900 B-LI-662.

LH120 C-1103, LH120 CG-1103.

LH150 C-1231, LH150 CPG-1229, LH150 ECPG-1229, LH150 CHR-1231,
LH150 ECG-1229, LH150 ECHR-1229.

Suitable for Liebherr Crawler Excavators Traction Drive with item code:

* 90008209 * 9443780 * 944378003 * 90212010 * * 90007697 * 90012140 * 90200164 * 9444340 * 90207592 *

Suitable for Liebherr Crawler Excavators:

E974B R-980, E974B-980.

ER974 B HD-1680, ER974 B-1688, ER974-980, ER974B HD-980, ER974B-980.

LOS1976-1402.

LOS-412.

LOS974 B-HD-737.

R964 BHDSL-760, R964 BSHD-938, R964 C SHD-1009, R964 C SHD-1278,
R964 C-SHD-1278, R964 CSHD-1009, R964 CSHD-1278, R964 CSHD-1447,
R964 CSHD-1448, R964 HDS-752, R964 SHD-1009, R964 SHD-938,
R964B HDSL-760, R964B SHD-938, R964 TR-655.

R966 S-HD-1535, R966 S-HD-1359.

R970 S-HD-1538, R970 S-HD-1571, R970 S-HD-1572, R970 S-HD-1772,
R970 S-HD-1784, R970 SME-1400, R970 SME-1401.

R974 B HD-408, R974 B-408, R974 B-601, R974 B-EW-796, R974 B-HD-408,
R974 B-HD-737, R974 B-HD-949, R974 B-LI-737, R974 BEW-608, R974 BEW-914,
R974 BHD-949, R974 BHDSL-451, R974 BHDSL-601, R974 BHDSL-737,
R974 BHDSL-742, R974 BHDSL-949, R974 BHDSL-988, R974 BHR-951,
R974 C HD-1137, R974 C HD-449, R974 C-HD-1137, R974 C-HD-1365,
R974 C-HD-1371, R974 C-HD-449, R974 C-HR-1059, R974 C-LCV-1417,
R974 CHDSL-1124, R974 CHDSL-1010, R974 CHR-1059, R974 CLCV-1417,
R974 HD-408, R974 HD-449, R974 HD-585, R974 HDSL-601, R974 HDSL-742,
R974 -408, R974-601, R974B EW-914, R974B HD-408, R974B HD-737,
R974B HD-949, R974B HDSL-451, R974B HDSL-585, R974B HDSL-601,
R974B HDSL-742, R974B HDSL-913, R974B HDSL-988, R974B HR-951,
R974B LIT-408.

R976 HD-1402, R976 HD-1428, R976 HD-1460, R976 HD-1540, R976 HD-1574,
R976 HD-1773, R976 HD-1785, R976 HD-SL-1540, R976 HDSL-1645, R976 LC-V-1461,
R976 LC-V-1540, R976 LC-V-1573, R976 LC-V-1773, R976 LC-V-1785.

R980 S-HD-1786, R980 S-HD-1543, R980 S-HD-1575, R980 S-HD-1576,
R980 S-HD-1774, R980 SME-1405, R980 VHHD-1786.

Suitable for Liebherr Mining Excavator Traction Drive with item code:

* 9443780 * 90003768 * 90007697 * 90013410 * 90203666 * * 90203990 * 9444130 * 970208301 *

Suitable for Liebherr Mining Excavators:

R9100-1132, R9100B-1132.

R9250-437, R9250E-1129.

R9350-1369, R9350-411, R9350E-1080, R9350E-771.

R984-409,

R994-411, R994BE-771.

The Multi-Disc Carrier is in Like New Condition

!! It is a Like New Multi-Disc Carrier !!

If you have any questions or visits, please feel free to contact me.